

## Technical Bulletin: Stacking of CEMEX Floor Beams



High risk of breaking the back of the lowest beam in stack



High risk of breaking the back of the middle and lowest beams in stack. Upper beams could also topple off stack.



Beams should be stacked on hard level ground with wooden bearers near their ends. Bearers should be vertically in line with each other

For further details or advise please contact :

CEMEX Floors Ltd, London Road, Wick, Bristol, BS30 5SJ

Tel 01179 373740

website: [www.cemex.co.uk](http://www.cemex.co.uk)

email: [gb-readyfloorsales@cemex.com](mailto:gb-readyfloorsales@cemex.com)